

- ~ Perfect match between drive station and energy consumption of grinding, energy saving to the fullest extent possible.
- ~ Forming a closed system with classifier, with negative pressure transport, without powder pollution.

应用范围(Application):

- ~ XJ MNYXZ [/ MC [/ [\ [/] ^ [/ [_ / % ` a `
- ~ b J MNY [c / - [/ d , e / f g h / i j [/ " # k l / m c n a `
- ~ Soft material: calcite, marble, limestone, barite, gypsum, slag etc.
- ~ Hard material: quartz, felspa, carbonundum, corundum, fine cement etc.

技术参数(Technical Parameter):

| • s Item | D * + # | | | | |
|---------------------------------|----------------------|------------|--------------------------------------|-------------------|--------------------------------|
| 1250s' [K(()) | 0.8 | 1 | 1.5 | 2 | 3 |
| | 1500 | 2200 | 3300 | 4000 | 7500 |
| | 1400 | 1900 | 2900 | 3500 | 6500 |
| | 1000 | 1400 | 2200 | 2700 | 4400 |
| | 450 | 580 | 880 | 1100 | 1760 |
| | § 1.5X5 | § 1.83X4.5 | § 1.83X6 | § 2.2X4 | § 2.2X6 , § 2.4X6 § 2.6X6 |
| | 110 | 160 | 220 | 250 | 560 |
| | HFW500 or HFW3315 | HFW4315 | HFW4400 or HFW6315 or 2HFW3315 | HFW3500 | HFW4500 or HFW6400 or 2H |
| | % 300 | % 380 | % 550 | or2HFW4315 500 | % 1130 |
| , - .) L ! Fliter area' m²# | 120 | 160 | 250 | % 700 250 | 500 |
| B- &O Thickness of dust | | | | | |

~ Y1 / > o p q r > t ! 1250 s] t u v (All of the parameters above are according to 1250 mesh GCC) `

2 / w T A P & N 9 x y z = > o p q { | p } (As different material from different places, the parameter is just for your reference) `